



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000968

DATE: 21-Jun-2019

## PRODUCT DISCONTINUANCE NOTICE

| Notice Type          | Maxim Part Number  | Recommended Replacement | Last Order Date | Last Delivery Date | Reason                                       |
|----------------------|--------------------|-------------------------|-----------------|--------------------|--|
| Reactivation         | DS1818R-20-U+      | N/A                     |                 |                    | Part reactivated from prior notice: M000969I |
| Reactivation         | DS28EL15X+U        | N/A                     |                 |                    | Part reactivated from prior notice: M000965I |
| Reactivation         | MAX16931BAGLS/VY+  | N/A                     |                 |                    | Part reactivated from prior notice: M000875  |
| Reactivation         | MAX16931BAGLS/VY+T | N/A                     |                 |                    | Part reactivated from prior notice: M000875  |
| Reactivation         | MAX19586ETN+D      | N/A                     |                 |                    | Part reactivated from prior notice: M000963I |
| Reactivation         | MAX19588ETN+D      | N/A                     |                 |                    | Part reactivated from prior notice: M000969I |
| Reactivation         | MAX20307DEMBD#     | N/A                     |                 |                    | Part reactivated from prior notice: M000948I |
| Reactivation         | MAX2694EWS+        | N/A                     |                 |                    | Part reactivated from prior notice: M000965I |
| Reactivation         | MAX2694EWS+T       | N/A                     |                 |                    | Part reactivated from prior notice: M000965I |
| Reactivation         | MAX6071AAUT30+     | N/A                     |                 |                    | Part reactivated from prior notice: M000969I |
| Lead-Free Conversion | STM1E-SFP24        | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT251AFQ-ADJ-008   | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT251AFQR-ADJ-008  | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT255BFQN-ADJ      | VT255BFQX-ADJ           | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT261ABWFQR-ADJ    | VT261ABWFQX-ADJ         | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT266BWFQ-ADJ      | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT266WFQ-ADJ-008   | VT266WFQ-ADJ            | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT7505FQ-ADJ       | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Lead-Free Conversion | VT7505FQX-ADJ      | N/A                     | 20-Jun-2020     | 19-Dec-2020        | Part can no longer be manufactured           |
| Discontinuance       | IC0400C782SF+LTB   | N/A                     | 20-Jun-2020     | 20-Dec-2020        | Part can no longer be manufactured           |
| Discontinuance       | MAX14713EWL+TCKA   | MAX14713EWL+T           | 20-Jun-2020     | 20-Dec-2020        | Part can no longer be manufactured           |
| Discontinuance       | MAX20307EVKIT#     | N/A                     | 21-Jun-2019     | 21-Jun-2019        | EVKIT is No Longer Supported                 |
| Discontinuance       | MAX20307EWL+T      | N/A                     | 21-Jun-2019     | 21-Jun-2019        | Part can no longer be manufactured           |
| Discontinuance       | MAXM17502ALI+      | MAXM17502ALI#           | 21-Jun-2019     | 21-Jun-2019        | The part was not released                    |
| Discontinuance       | MAXM17502ALI+T     | MAXM17502ALI#T          | 21-Jun-2019     | 21-Jun-2019        | The part was not released                    |
| Discontinuance       | STM1E-SFP22        | N/A                     | 21-Jun-2019     | 21-Jun-2019        | Part can no longer be manufactured           |

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Jul-2019

|                |                 |                 |             |             |                                    |
|----------------|-----------------|-----------------|-------------|-------------|------------------------------------|
| Discontinuance | STM1E-SFP23     | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | STM1E-SFP26     | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1156SAFQR     | VT1156SAFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1165SFQR      | VT1165SFQX      | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1175MAFPR     | VT1175MAFPX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1175SFQR      | VT1175SFQX      | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1185MFPR      | VT1185MFPX      | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1189SAFQR     | VT1189SAFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1195SFQR-001  | VT1195SFQX-001  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1198SBFQR     | VT1198SBFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1526MBFQR     | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1536MBFQR     | VT1536MBFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1547MBFQR     | VT1547MBFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1577MAFQR     | VT1577MAFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1626SFQR      | VT1626SFQX      | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT1656SAFQR     | VT1656SAFQX     | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT233TFCR-ADJ   | VT233TFCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT233WFCX-ADJ   | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT238AWFQR-ADJ  | VT238AWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT241WFCR-ADJ   | VT241WFCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT242WFCR-ADJ   | VT242WFCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT243WFCR-ADJ   | VT243WFCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT245ABWFQR-ADJ | VT245ABWFQX-ADJ | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT245AWFQR-ADJ  | VT245AWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT246BWFQR-ADJ  | VT246BWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT247BWFQR-ADJ  | VT247BWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT247WFQR-ADJ   | VT247WFQX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT248BWFQ-ADJ   | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT248BWFQR-ADJ  | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT248BWFQX-ADJ  | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT2491FCR-ADJ   | VT2491FCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT2492AFQR-ADJ  | VT2492AFCX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT251AFQR-ADJ   | VT251AFQX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT255FQN-ADJ    | VT255FQX-ADJ    | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT260WFQR-ADJ   | VT260WFQX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT261BWFQR-ADJ  | VT261BWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Jul-2019**

|                |                 |                 |             |             |                                    |
|----------------|-----------------|-----------------|-------------|-------------|------------------------------------|
| Discontinuance | VT263ABWFQR-ADJ | VT263ABWFQX-ADJ | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT263AWFQR-ADJ  | VT263AWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT263BWFQR-ADJ  | VT263BWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT263WFQR-ADJ   | VT263WFQX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT266AWFQR-ADJ  | VT266AWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT267AWFQR-ADJ  | VT267AWFQX-ADJ  | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT271MFP        | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT271MFPR       | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT271MFPX       | N/A             | 21-Dec-2019 | 20-Dec-2020 | Part can no longer be manufactured |
| Discontinuance | VT271SFQR       | VT271SFQX       | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT281BFCR-ADJ   | VT281BFCX-ADJ   | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT285FQN-ADJ    | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT285FQR-ADJ    | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT285FQX-ADJ    | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT500FQR        | VT500FQX        | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT501FQR        | VT501FQX        | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |
| Discontinuance | VT7505FQR-ADJ   | N/A             | 21-Jun-2019 | 21-Jun-2019 | Part can no longer be manufactured |