

Issue date: January 6, 2020
PTN No.: (Application No 1019006)

(name) Takeshi Tsujii
(job title) Manager
(Division) LSI HQ ATP Div

ROHM Co., Ltd.

Notification of Product Discontinuance

Dear Valued Customer

This letter intends as a formal notification that ROHM Co., Ltd. is discontinuing the production of the following product. We acknowledges the obligation to promptly inform our customers of the intent to exit products to enable out customers the ability to prepare for alternatives and/or assist in our product portfolio renewal process.

It would be very appreciated if you could your reply by 2/8/2020

Your early reply in this regard would be very much appreciated.

Product category	Affected part number(s)	Suggested replacement product
IC	attached	n/a
<u>Reason for discontinuance</u> Avoiding production trouble by aging WA Test Equipment. We can't receive enough support because of Aging WA Tester have passed over than ten years after finishing production of it. It is very difficult to repair (or takes long time to fix) once in case of trouble occurred.		
<u>Last Time Buy</u> 31-Mar-20		
<u>Last Time Ship</u> 30-Apr-20 Production will have finished after produce your last buy QTY		

Lack of response by the customer after 30 days constitutes acceptance of the change noted.

ROHM EOL # 1019006

BA1604F-E2	BA6820F-E2
BA6247FP-YE2	BA6822F
BA032LBSG-TR	BA6822F-E2
BA036LBSG-TR	BA7603F-E2
BA038LBSG-TR	BU2624AF-E2
BA040LBSG-TR	BU2630F
BA050LBSG-TR	BU2630F-E2
BA3308FV	BU2630FV
BA3416BL	BU3618K
BA3430FS	BU4S01-TR
BA3430FS-E2	BU4S11-TR
BA3430S	BU4S584-TR
BA3812L	BU4S66-TR
BA5152F	BU4S71-TR
BA5204F	BU4S81-TR
BA6161F	BU4SU69-TR
BA6161F-E2	BU8242F-E2
BA6208F	BU8244F-E2
BA6208F-E2	BU8772KN
BA7603F-BZE2	BU8772KN-E2
BU2114F-E2	BU8874F
BU2611AF-E2	BU8874F-E2
BU9817FV-E2	BU9817FV
BA6266F	BA1604F-BZE2
BA6820F	