

MKT_NO	NOTICE_TYPE	ISSU_DATE	LAST_ORDER_DATE	LAST_SHIP_DATE	REASON	RECOMMENDED_REPLACEMENT
LM75BIMM-3+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000773I	N/A
MAX6314US44D2-T	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6314US44D2+T
MAX6421US29	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6421US29+
MAX6314US44D2	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6314US44D2+
MAX812LEUS-T	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX812LEUS+T
MAX6315US26D2	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6315US26D2+
MAX6314US26D2	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6314US26D2+
MAX811LEUS-T	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX811LEUS+T
MAX6315US46D2-T	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6315US46D2+T
MAX6314US46D3	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6314US46D3+
MAX837EUS-T	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX837EUS+T
MAX6467US26D3	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6467US26D3+
MAX6314US25D1	Lead-Free Conversion	8/14/2015	2/14/2016	8/14/2017	Leaded with a Lead-Free Replacement	MAX6314US25D1+
MAX14706EVAL#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14707DEMBD#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14707ENA+	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14707EVAL#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14708DEMBD#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14708EVAL#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14706ENA+	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14706ENA+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14707ENA+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14708ENA+	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14708ENA+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAX14706DEMBD#	Reactivation	8/14/2015			Part reactivated from prior notice: M000790	N/A
MAXQ616V-L001+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000783	N/A
MAX7461EUK+T	Reactivation	8/14/2015			Part reactivated from prior notice: M000805	N/A
MAX7461EUK+	Reactivation	8/14/2015			Part reactivated from prior notice: M000805	N/A
MAX3043ESE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX3043ESE+
MAX313LESE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX313LESE+
MAX4608CSE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX4608CSE+
MAX4621CSE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX4621CSE+
MAX4633CSE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX4633CSE+
MAX4709ESE	Lead-Free Conversion	8/14/2015	11/16/2015	8/14/2017	Leaded with a Lead-Free Replacement	MAX4709ESE+
MAX17140ETL+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Part can no longer be manufactured	N/A

MAX17140ETL+T	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Part can no longer be manufactured	N/A
DS2174QN+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Part can no longer be manufactured	N/A
MAX16831ATJ/V+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	The part was not released	N/A
MAX1518ETJ+	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX8751ETJ+	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX8785AEVKIT#	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX1785EUU+GH8	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1785EUU+T	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1785EUU+TGH8	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1785EVMINIQU#	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX1786AEUI+T	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1786AEUI+TG069	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1788EUI+T	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1788EUI+TG069	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1787EUI+GH8	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1787EUI+TGH8	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1789EUI+	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1789EUI+T	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
MAX1789EVKIT+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX1789UCLDR+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX16953AEE/V+TCHL	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Part can no longer be manufactured	MAX16953AEE/V+T
MAX9662EFR+T	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
VT231TFCR-ADJ	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Mini-reel option no longer available	VT231TFCX-ADJ
VT1155MFQR	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Mini-reel option no longer available	VT1155MFQX
71M6511-DB	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	71M6541F-DB
78M6612-DB/OMU-RF	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6612-DB/OMU-USB	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6612-EVM-1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6612SP-EVM-1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6613-EVM-1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6610+LMU/EK#1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
78M6610+PSU/EK#1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+PSUEVK1#
MAX2986EVKIT#	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX98357EVKIT#TQFN	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	N/A
MAX17116ETG+	Discontinuance	8/14/2015	2/14/2016	2/13/2018	Part can no longer be manufactured	N/A
DS2174Q+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	Part can no longer be manufactured	N/A
78M6613-PSU-1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+PSUEVK1#

78M6613-SP-1	Discontinuance	8/14/2015	8/14/2015	8/14/2017	EVKIT is No Longer Supported	78M6610+LMUEVK1#
MAX16995ATPA/V+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	The part was not released	MAX16995ATPF/V+
MAX16995ATPB/V+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	The part was not released	MAX16995ATPG/V+
MAX16995ATPC/V+	Discontinuance	8/14/2015	2/14/2016	2/13/2018	The part was not released	MAX16995ATPH/V+
MAX16995ATPD/V+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	The part was not released	MAX16995ATPI/V+
MAX16995ATPE/V+	Discontinuance	8/14/2015	8/14/2015	8/14/2017	The part was not released	MAX16995ATPJ/V+