

PRODUCT CHANGE NOTIFICATION

#PCN-DC-DM6H-13

Business Unit	Product Line Code	Type of Change	Action	Date of issue
DC	ABQ	Aesthetic	Notify Distributors and Field	2/8/2013

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description of Change:

Change in the color of the contact carrier

The color of the grip of D-coded contact carriers will be changed from black to green. With the change in the color, the M12 port will be marked as a fieldbus interface. The color change also serves as visual coding that prevents incorrect plugging.

Warranty Information:

Stock Status

Can existing stock still be used? Y


Is mixture of stock acceptable? N

Transaction Dates:

Date modification goes into effect from Germany: 12/13/2012

Expected first shipment (from Phoenix Contact) of the modified product(s): 7/1/2013

PRODUCT CHANGE NOTIFICATION



Should you have any issues with the timeline or content of this change, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

LYNDSEY WALLING
Marketing lead Specialist
(800)888-7388x3722
lwalling@phoenixcon.com

Thank you,



Steve Barber,
Product Marketing Manager

Part#	Type Description
1534627	SACC-DSIV-M12FSD-4CON-L180
1534630	SACC-DSIV-M12FSD-4CON-L90
1434866	SACC-DSIV-M12MSD-4CON-L90