

## Product Advisory

Issue Date: December 21, 2022

**Change Type:**

Packaging update for NICs to consolidate labeling.


**Description and Extent of Change:**

The NIC Serial Number and Carton ID labels will be consolidated into the Bulk ID label.

**Current Carton Label**



**New Carton Label**



**Reasons for Change:**

The change is being implement to further enhance supply continuity and standardize package labeling across the product line.



**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.

**Effective Date of Change:**

The part number revision will be incremented to track this update. Product shipments start after February 1, 2023.

**Parts Affected:**

Part Number	Revision Number	New Revision Number
BCM95719A1904AC	18	19
BCM95719N1905C	13	14
BCM95719N1905CI	2	3
BCM95720A2003AC	15	16
BCM95720A2003ACBLK	14	15
BCM957412A4120AC	17	18
BCM957412M4122C	14	15
BCM957412N4120C	19	20
BCM957412N4120CI	4	5
BCM957414A4140C	12	13
BCM957414A4142CC	20	21
BCM957414M4142C	15	16
BCM957414M4143C	16	17
BCM957414N4140C	20	21
BCM957416A4160C	11	12
BCM957416M4163C	10	11
BCM957416N4160C	15	16
BCM957416N4160CI	3	4
BCM957502-N150FGB	5	6
BCM957502-N150G	13	14
BCM957504-M1100G16	10	11
BCM957504-M1100GB	6	7
BCM957504-M1100GBQ	6	7
BCM957504-N1100FH	3	4
BCM957504-N1100FXB	5	6
BCM957504-N1100FY4	5	6
BCM957504-N1100FY4Q	5	6
BCM957504-N1100FYB	4	5
BCM957504-N1100FYC	4	5
BCM957504-N1100FYCQ	8	9
BCM957504-N1100FZB	5	6
BCM957504-N1100G	29	30
BCM957504-N1100GD	6	7
BCM957504-N1100GI	5	6
BCM957504-N2100GI	2	3
BCM957504-N425G	29	30



BCM957504-P425G	21	22
BCM957508-N1200FX	3	4
BCM957508-N1200FXQ	4	5
BCM957508-N1200FY4	2	3
BCM957508-N1200FZ	2	3
BCM957508-N1200FZQ	3	4
BCM957508-N2100G	28	29
BCM957508-N2100GD	4	5
BCM957508-N2100GDQ	5	6
BCM957508-N2100GI	3	4
BCM957508-P1200G	2	3
BCM957508-P2100G	27	28
BCM957508-P2100GQ	6	7

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.