

Product Change Notification

(Notification - P2012064p-DIG)

(SAF-B-20-0010)

December 15, 2020

To: *Our Valued Digi-Key Electronics Customer*

Overview: The purpose of this notification is to communicate a product change of select Renesas Electronics America, Inc. (REA) devices. These devices have suggested replacements.

Affected Products: A review of our records indicates the list of products in the Appendix may affect your company.

Part numbers given in this list are for active part numbers in REA database at the time of this notification.

Key Dates:

Final last time buy (LTB) orders of original part number placed to REA or to a franchised REA distributor.	December 15th, 2021
Planned date for last time shipment (LTS) from REA.	December 30th, 2022

Response: Please place last time buy (LTB) orders in a timely manner prior to the key dates listed to avoid product availability issues. If you anticipate volumes beyond your regular rate, please contact your REA sales representative with a forecast of your requirements. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas' General Terms and Conditions of Sale (<https://www.renesas.com/us/en/legal/terms-and-conditions.html>) or the applicable legal terms covering the purchase and sale transaction. Renesas will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

You are encouraged to sample the suggested replacement device and begin qualification as soon as possible. Please contact your REA sales representative to obtain samples.

Please contact your REA sales representative for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics America, Inc.

Appendix: Digi-Key Affected Part List

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
BCR08AM-12A#B00	BCR08AM-12A#BD0	BCR8PM-12LB#B01	BCR8FM-12LB#BH0
BCR08AM-12A-TB#B00	BCR08AM-12A-TB#BD0	BCR8PM-12LD#B00	BCR8FM-12LC#BG0
BCR08AM-14A#B00	BCR08AM-14A#BD0	BCR8PM-12LE#B00	BCR8FM-12LB#BG0
BCR08AM-14A-A6#B00	BCR08AM-14A-A6#BD0	BCR8PM-12LG#B00	BCR8FM-12LB#BG0
BCR10PM-12LD#B00	BCR10FM-12LC#BG0	BCR8PM-14LE#B00	BCR8FM-14LB#BG0
BCR10PM-12LG#B00	BCR10FM-12LB#BG0	BCR8PM-14LG#B00	BCR8FM-14LB#BG0
BCR10PM-14LJ#B00	BCR10FM-14LJ#BG0	BCR8PM-14LJ#B00	BCR8FM-14LJ#BG0
BCR12PM-12LA#B00	BCR12FM-12LB#BH0	BCR8PM-16LG#B00	BCR8FM-16LB#BG0
BCR12PM-12LAA8#B00	BCR12FM-12LBA8#BH0	BCR8PM-20LA#B00	BCR8FM-20LA#BH0
BCR12PM-12LC#B00	BCR12FM-12LC#BG0	CR02AM-8#F00	CR02AM-8#BD0
BCR12PM-12LD#B00	BCR12FM-12LC#BG0	CR03AM-16A#B00	CR03AM-16A#BD0
BCR12PM-12LG#B00	BCR12FM-12LB#BG0	CR04AM-12A-TB#B00	CR04AM-12A-TB#BD0
BCR12PM-14LG#B00	BCR12FM-14LB#BG0	CR05AM-16A#B00	CR05AM-16A#BD0
BCR12PM-14LJ#B00	BCR12FM-14LJ#BG0	CR05BM-12A#B00	CR05BM-12A#BD0
BCR16PM-12LA#B00	BCR16FM-12LB#BH0	CR12PM-12B#B00	CR12FM-12B#BH0
BCR16PM-12LC#B00	BCR16FM-12LC#BG0	CR3PM-12G#B00	CR3CS-12A-A1#BH0
BCR16PM-12LD#B00	BCR16FM-12LC#BG0	CR6PM-12G#B00	CR6FM-12B#BG0
BCR16PM-12LG#B00	BCR16FM-12LB#BG0	CR8PM-12B#B00	CR8FM-12B#BH0
BCR16PM-14LG#B00	BCR16FM-14LB#BG0	MC-10281F5-LN7-A	MC-10281AF5-LN7-A
BCR16PM-14LJ#B00	BCR16FM-14LJ#BH0	R5F109GAJFB#H0	R5F109GACJFB#10
BCR16PM-16LH#B00	BCR16FM-16LH#BG0	R5F109GAJFB#V0	R5F109GACJFB#30
BCR16PM-16LH-1#B00	BCR16FM-16LH-1#BG0	R5F109GAJFB#V0Q	R5F109GACJFB#30Q
BCR16PM-16LH-1#COA	BCR16FM-16LH-1#BG0	R5F109GAJFB#X0	R5F109GACJFB#50
BCR1AM-12A#C01	BCR1AM-12A#BD0	R5F109GAJJ00FB#HOQ	R5F109GACJJ00FB10Q
BCR1AM-12A-TB#C01	BCR1AM-12A-TB#BD0	R5F109GAJJ01FB#HOQ	R5F109GACJJ01FB10Q
BCR1AM-8P#B00	BCR1AM-8P#BD0	R5F109GAKFB#HOQ	R5F109GACKFB#10Q
BCR20PM-14LJ#B00	BCR20FM-14LJ#BH0	R5F109GAKFB#V0	R5F109GACKFB#30
BCR25PM-14LJ#B00	BCR25FM-14LJ#BH0	R5F109GAKFB#V0Q	R5F109GACKFB#30Q
BCR3AM-12B#B00	BCR3AM-12B#BD0	R5F109GAKFB#X0	R5F109GACKFB#50
BCR3AM-14B#B00	BCR3AM-14B#BD0	R5F109GAKFB#X0G	R5F109GACKFB#50G
BCR3PM-12LG#B00	BCR3FM-12LB#BG0	R5F109GAKFB#X0Q	R5F109GACKFB#50Q
BCR3PM-14LG#B00	BCR3FM-14LB#BG0	R5F109GBJFB#V0	R5F109GBCJFB#30
BCR5PM-12LG#B00	BCR5FM-12LB#BG0	R5F109GBJFB#V0G	R5F109GBCJFB#30G
BCR5PM-14LD#B00	BCR5FM-14LC#BG0	R5F109GBJFB#X0	R5F109GBCJFB#50
BCR5PM-14LD-A8#B00	BCR5FM-14LC-A8#BG0	R5F109GBJFB#X0G	R5F109GBCJFB#50G
BCR5PM-14LG#B00	BCR5FM-14LB#BG0	R5F109GBKFB#V0	R5F109GBCKFB#30
BCR5PM-14LJ#B00	BCR5FM-14LJ#BG0	R5F109GBKFB#X0	R5F109GBCKFB#50
BCR8PM-12LA#B00	BCR8FM-12LB#BH0	R5F109GCJFB#H0	R5F109GCCJFB#10

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F109GCJFB#V0	R5F109GCCJFB#30	R5F109LCKFB#X0	R5F109LCCKFB#50
R5F109GCJFB#VOG	R5F109GCCJFB#30G	R5F109LDJFB#V0	R5F109LDCJFB#30
R5F109GCJFB#X0	R5F109GCCJFB#50	R5F109LDJFB#X0	R5F109LDCJFB#50
R5F109GCJFB#X0G	R5F109GCCJFB#50G	R5F109LDKFB#H0	R5F109LDCKFB#10
R5F109GCKFB#H0Q	R5F109GCKFB#10Q	R5F109LDKFB#V0	R5F109LDCKFB#30
R5F109GCKFB#V0	R5F109GCKFB#30	R5F109LDKFB#X0	R5F109LDCKFB#50
R5F109GCKFB#VOG	R5F109GCKFB#30G	R5F109LEJFB#V0	R5F109LECJFB#30
R5F109GCKFB#V0Q	R5F109GCKFB#30Q	R5F109LEJFB#X0	R5F109LECJFB#50
R5F109GCKFB#X0	R5F109GCKFB#50	R5F109LEKFB#H0	R5F109LECKFB#10
R5F109GCKFB#X0Q	R5F109GCKFB#50Q	R5F109LEKFB#V0	R5F109LECKFB#30
R5F109GDJFB#V0	R5F109GDCJFB#30	R5F109LEKFB#VOG	R5F109LECKFB#30G
R5F109GDJFB#X0	R5F109GDCJFB#50	R5F109LEKFB#X0	R5F109LECKFB#50
R5F109GDJFB#X0G	R5F109GDCJFB#50G	R5F10AGAKFB#V5	R5F10AGACKFB#35
R5F109GDKFB#V0	R5F109GDCKFB#30	R5F10AGAKFB#X5	R5F10AGACKFB#55
R5F109GDKFB#X0	R5F109GDCKFB#50	R5F10AGALFB#V5	R5F10AGACLFB#35
R5F109GEJFB#H0	R5F109GECJFB#10	R5F10AGALFB#X5	R5F10AGACLFB#55
R5F109GEJFB#H0G	R5F109GECJFB#10G	R5F10AGCKFB#H5	R5F10AGCCKFB#15
R5F109GEJFB#V0	R5F109GECJFB#30	R5F10AGCKFB#V5	R5F10AGCCKFB#35
R5F109GEJFB#X0	R5F109GECJFB#50	R5F10AGCKFB#X5	R5F10AGCCKFB#55
R5F109GEJFB#X0G	R5F109GECJFB#50G	R5F10AGCLFB#H5	R5F10AGCCLFB#15
R5F109GEKFB#V0	R5F109GECKFB#30	R5F10AGCLFB#V5	R5F10AGCCLFB#35
R5F109GEKFB#VOG	R5F109GECKFB#30G	R5F10AGCLFB#X5	R5F10AGCCLFB#55
R5F109GEKFB#X0	R5F109GECKFB#50	R5F10AGDKFB#V5	R5F10AGDCKFB#35
R5F109GEKFB#X0G	R5F109GECKFB#50G	R5F10AGDKFB#X5	R5F10AGDCKFB#55
R5F109LAJFB#V0	R5F109LACJFB#30	R5F10AGDLFB#V5	R5F10AGDCLFB#35
R5F109LAJFB#X0	R5F109LACJFB#50	R5F10AGDLFB#X5	R5F10AGDCLFB#55
R5F109LAKFB#V0	R5F109LACKFB#30	R5F10AGEKFB#V5	R5F10AGECKFB#35
R5F109LAKFB#VOG	R5F109LACKFB#30G	R5F10AGEKFB#X5	R5F10AGECKFB#55
R5F109LAKFB#X0	R5F109LACKFB#50	R5F10AGELFB#V5	R5F10AGECLFB#35
R5F109LAKFB#X0G	R5F109LACKFB#50G	R5F10AGELFB#V5Q	R5F10AGECLFB#35Q
R5F109LBJFB#V0	R5F109LBCJFB#30	R5F10AGELFB#X5	R5F10AGECLFB#55
R5F109LBJFB#X0	R5F109LBCJFB#50	R5F10AGFKFB#V5	R5F10AGFCKFB#35
R5F109LBJFB#X0G	R5F109LBCJFB#50G	R5F10AGFKFB#X5	R5F10AGFCKFB#55
R5F109LBKFB#V0	R5F109LBCKFB#30	R5F10AGFLFB#H5	R5F10AGFCLFB#15
R5F109LBKFB#X0	R5F109LBCKFB#50	R5F10AGFLFB#V5	R5F10AGFCLFB#35
R5F109LCJFB#V0	R5F109LCCJFB#30	R5F10AGFLFB#X5	R5F10AGFCLFB#55
R5F109LCJFB#X0	R5F109LCCJFB#50	R5F10AGGKFB#V5	R5F10AGGCKFB#35
R5F109LCKFB#V0	R5F109LCCKFB#30	R5F10AGGKFB#X5	R5F10AGGCKFB#55

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F10AGGLFB#H5	R5F10AGGCLFB#15	R5F10AMGLFB#X5	R5F10AMGCLFB#55
R5F10AGGLFB#H5Q	R5F10AGGCLFB#15Q	R5F10BGCKFB#V5	R5F10BGCKFB#35
R5F10AGGLFB#V5	R5F10AGGCLFB#35	R5F10BGCKFB#V5Q	R5F10BGCKFB#35Q
R5F10AGGLFB#V5Q	R5F10AGGCLFB#35Q	R5F10BGCKFB#X5	R5F10BGCKFB#55
R5F10AGGLFB#X5	R5F10AGGCLFB#55	R5F10BGCLFB#V5	R5F10BGCLFB#35
R5F10ALCKFB#V5	R5F10ALCKFB#35	R5F10BGCLFB#X5	R5F10BGCLFB#55
R5F10ALCKFB#X5	R5F10ALCKFB#55	R5F10BGDKFB#V5	R5F10BGDKFB#35
R5F10ALCLFB#V5	R5F10ALCCLFB#35	R5F10BGDKFB#X5	R5F10BGDKFB#55
R5F10ALCLFB#X5	R5F10ALCCLFB#55	R5F10BGDLFB#V5	R5F10BGDLFB#35
R5F10ALDKFB#V5	R5F10ALDCKFB#35	R5F10BGDLFB#X5	R5F10BGDLFB#55
R5F10ALDKFB#X5	R5F10ALDCKFB#55	R5F10BGEKFB#V5	R5F10BGEKFB#35
R5F10ALDLFB#V5	R5F10ALDCLFB#35	R5F10BGEKFB#X5	R5F10BGEKFB#55
R5F10ALDLFB#X5	R5F10ALDCLFB#55	R5F10BGEKFB#V5	R5F10BGEKFB#35
R5F10ALEKFB#V5	R5F10ALECKFB#35	R5F10BGEKFB#X5	R5F10BGEKFB#55
R5F10ALEKFB#X5	R5F10ALECKFB#55	R5F10BGEKFB#V5Q	R5F10BGEKFB#35Q
R5F10ALELFB#V5	R5F10ALECLFB#35	R5F10BGEKFB#X5	R5F10BGEKFB#55
R5F10ALELFB#X5	R5F10ALECLFB#55	R5F10BGELFB#V5	R5F10BGELFB#35
R5F10ALFKFB#V5	R5F10ALFCKFB#35	R5F10BGELFB#X5	R5F10BGELFB#55
R5F10ALFKFB#X5	R5F10ALFCKFB#55	R5F10BGELFB#V5Q	R5F10BGELFB#35Q
R5F10ALFLFB#V5	R5F10ALFCLFB#35	R5F10BGELFB#X5	R5F10BGELFB#55
R5F10ALFLFB#X5	R5F10ALFCLFB#55	R5F10BGFKFB#V5	R5F10BGFKFB#35
R5F10ALGKFB#V5	R5F10ALGCKFB#35	R5F10BGFKFB#X5	R5F10BGFKFB#55
R5F10ALGKFB#X5	R5F10ALGCKFB#55	R5F10BGFLFB#H5	R5F10BGFLFB#15
R5F10ALGLFB#H5	R5F10ALGCLFB#15	R5F10BGFLFB#V5	R5F10BGFLFB#35
R5F10ALGLFB#V5	R5F10ALGCLFB#35	R5F10BGFLFB#X5	R5F10BGFLFB#55
R5F10ALGLFB#V5Q	R5F10ALGCLFB#35Q	R5F10BGGLFB#V5	R5F10BGGLFB#35
R5F10ALGLFB#X5	R5F10ALGCLFB#55	R5F10BGGLFB#X5	R5F10BGGLFB#55
R5F10AMEKFB#V5	R5F10AMECKFB#35	R5F10BGGLFB#H5	R5F10BGGLFB#15
R5F10AMEKFB#X5	R5F10AMECKFB#55	R5F10BGGLFB#H5Q	R5F10BGGLFB#15Q
R5F10AMELFB#V5	R5F10AMECLFB#35	R5F10BGGLFB#V5	R5F10BGGLFB#35
R5F10AMELFB#X5	R5F10AMECLFB#55	R5F10BGGLFB#V5Q	R5F10BGGLFB#35Q
R5F10AMFKFB#V5	R5F10AMFCKFB#35	R5F10BGGLFB#X5	R5F10BGGLFB#55
R5F10AMFKFB#X5	R5F10AMFCKFB#55	R5F10BGGLFB#X5Q	R5F10BGGLFB#55Q
R5F10AMFLFB#V5	R5F10AMFCLFB#35	R5F10BLCKFB#V5	R5F10BLCKFB#35
R5F10AMFLFB#X5	R5F10AMFCLFB#55	R5F10BLCKFB#X5	R5F10BLCKFB#55
R5F10AMGKFB#V5	R5F10AMGCKFB#35	R5F10BLCLFB#V5	R5F10BLCLFB#35
R5F10AMGKFB#X5	R5F10AMGCKFB#55	R5F10BLCLFB#X5	R5F10BLCLFB#55
R5F10AMGLFB#V5	R5F10AMGCLFB#35	R5F10BLDKFB#V5	R5F10BLDKFB#35
		R5F10BLDKFB#X5	R5F10BLDKFB#55
		R5F10BLDLFB#V5	R5F10BLDLFB#35
		R5F10BLDLFB#X5	R5F10BLDLFB#55
		R5F10BLEKFB#V5	R5F10BLEKFB#35

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F10BLEKFB#X5	R5F10BLECKFB#55	R5F10CLDLFB#V2	R5F10CLDCLFB#32
R5F10BLELFB#V5	R5F10BLECLFB#35	R5F10CLDLFB#V2G	R5F10CLDCLFB#32G
R5F10BLFKFB#V5	R5F10BLFKFB#35	R5F10CLDLFB#X6	R5F10CLDCLFB#56
R5F10BLFKFB#X5	R5F10BLFKFB#55	R5F10CMDJFB#V2G	R5F10CMDCLFB#32G
R5F10BLFLFB#V5	R5F10BLFLFB#35	R5F10CMDLFB#V2	R5F10CMDCLFB#32
R5F10BLFLFB#X5	R5F10BLFLFB#55	R5F10CMDLFB#V2G	R5F10CMDCLFB#32G
R5F10BLGKFB#V5	R5F10BLGCKFB#35	R5F10CMEJFB#V2	R5F10CMECLFB#32
R5F10BLGKFB#X5	R5F10BLGCKFB#55	R5F10CMEJFB#V2G	R5F10CMECLFB#32G
R5F10BLGLFB#H5	R5F10BLGCLFB#15	R5F10CMEJFB#X6G	R5F10CMECLFB#56G
R5F10BLGLFB#V5	R5F10BLGCLFB#35	R5F10CMEJFB#V2G	R5F10CMECLFB#32G
R5F10BLGLFB#X5	R5F10BLGCLFB#55	R5F10DGCJFB#V2G	R5F10DGCCLFB#32G
R5F10BMEKFB#V5	R5F10BMECKFB#35	R5F10DGCJFB#V2G	R5F10DGCCLFB#32G
R5F10BMEKFB#X5	R5F10BMECKFB#55	R5F10DGDJFB#V2	R5F10DGDCLFB#32
R5F10BMELFB#V5	R5F10BMECLFB#35	R5F10DGDJFB#V2G	R5F10DGDCLFB#32G
R5F10BMELFB#X5	R5F10BMECLFB#55	R5F10DGDJFB#X6	R5F10DGDCLFB#56
R5F10BMFKFB#V5	R5F10BMFKFB#35	R5F10DGDJFB#X6G	R5F10DGDCLFB#56G
R5F10BMFKFB#X5	R5F10BMFKFB#55	R5F10DGDJFB#V2G	R5F10DGDCLFB#32G
R5F10BMFLFB#V5	R5F10BMFLFB#35	R5F10DGEJFB#V2G	R5F10DGECLFB#32G
R5F10BMFLFB#X5	R5F10BMFLFB#55	R5F10DGEJFB#V2G	R5F10DGECLFB#32G
R5F10BMGKFB#V5	R5F10BMGCKFB#35	R5F10DLDJFB#H2	R5F10DLDCJFB#12
R5F10BMGKFB#X5	R5F10BMGCKFB#55	R5F10DLDJFB#V2	R5F10DLDCJFB#32
R5F10BMGLFB#H5Q	R5F10BMGCLFB#15Q	R5F10DLDJFB#V2G	R5F10DLDCJFB#32G
R5F10BMGLFB#V5	R5F10BMGCLFB#35	R5F10DLDJFB#X6	R5F10DLDCJFB#56
R5F10BMGLFB#X5	R5F10BMGCLFB#55	R5F10DLDLFB#V2G	R5F10DLDCJFB#32G
R5F10CGBJFB#V2	R5F10CGBCLFB#32	R5F10DLEJFB#V2	R5F10DLECLFB#32
R5F10CGBJFB#V2G	R5F10CGBCLFB#32G	R5F10DLEJFB#V2G	R5F10DLECLFB#32G
R5F10CGBJFB#X6	R5F10CGBCLFB#56	R5F10DLEJFB#V2Q	R5F10DLECLFB#32Q
R5F10CGBJFB#X6G	R5F10CGBCLFB#56G	R5F10DLEJFB#X6	R5F10DLECLFB#56
R5F10CGBLFB#V2	R5F10CGBCLFB#32	R5F10DLEJFB#X6G	R5F10DLECLFB#56G
R5F10CGBLFB#V2G	R5F10CGBCLFB#32G	R5F10DLELFB#V2	R5F10DLECLFB#32
R5F10CGBLFB#X6	R5F10CGBCLFB#56	R5F10DLELFB#V2G	R5F10DLECLFB#32G
R5F10CGBLFB#X6G	R5F10CGBCLFB#56G	R5F10DMDJFB#V2G	R5F10DMDCLFB#32G
R5F10CGCJFB#V2G	R5F10CGCCJFB#32G	R5F10DMDLFB#V2G	R5F10DMDCLFB#32G
R5F10CGCLFB#V2G	R5F10CGCCLFB#32G	R5F10DMEJFB#H2	R5F10DMECLFB#12
R5F10CGDJFB#V2G	R5F10CGDCJFB#32G	R5F10DMEJFB#V2	R5F10DMECLFB#32
R5F10CGDLFB#V2G	R5F10CGDCLFB#32G	R5F10DMEJFB#V2G	R5F10DMECLFB#32G
R5F10CLDJFB#V2	R5F10CLDCJFB#32	R5F10DMEJFB#X6	R5F10DMECLFB#56
R5F10CLDJFB#V2G	R5F10CLDCJFB#32G	R5F10DMEJFB#X6G	R5F10DMECLFB#56G

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F10DMELFB#V2G	R5F10DMECLFB#32G	R5F10DPJLFB#V2G	R5F10DPJCLFB#32G
R5F10DMELFB#X6G	R5F10DMECLFB#56G	R5F10DPJLFB#X6	R5F10DPJCLFB#56
R5F10DMFJFB#V2G	R5F10DMFCJFB#32G	R5F10DPJLFB#X6G	R5F10DPJCLFB#56G
R5F10DMFLFB#V2G	R5F10DMFCLFB#32G	R5F10PGDKFB#V5	R5F10PGDCKFB#35
R5F10DMGJFB#V2G	R5F10DMGJFB#32G	R5F10PGDKFB#X5	R5F10PGDCKFB#55
R5F10DMGLFB#V2	R5F10DMGCLFB#32	R5F10PGDLFB#V5	R5F10PGDCLFB#35
R5F10DMGLFB#V2G	R5F10DMGCLFB#32G	R5F10PGDLFB#X5	R5F10PGDCLFB#55
R5F10DMJJFB#V2	R5F10DMJCJFB#32	R5F10PGEKFB#V5	R5F10PGECKFB#35
R5F10DMJJFB#V2G	R5F10DMJCJFB#32G	R5F10PGEKFB#X5	R5F10PGECKFB#55
R5F10DMJLFB#V2	R5F10DMJCLFB#32	R5F10PGELFB#V5	R5F10PGECLFB#35
R5F10DMJLFB#V2G	R5F10DMJCLFB#32G	R5F10PGELFB#X5	R5F10PGECLFB#55
R5F10DPEJFB#V2	R5F10DPECJFB#32	R5F10PGFKFB#V5	R5F10PGFCKFB#35
R5F10DPEJFB#V2G	R5F10DPECJFB#32G	R5F10PGFKFB#X5	R5F10PGFCKFB#55
R5F10DPEJFB#X6	R5F10DPECJFB#56	R5F10PGFLFB#V5	R5F10PGFCLFB#35
R5F10DPEJFB#X6G	R5F10DPECJFB#56G	R5F10PGFLFB#X5	R5F10PGFCLFB#55
R5F10DPELFB#H2	R5F10DPECLFB#12	R5F10PGGKFB#V5	R5F10PGGCKFB#35
R5F10DPELFB#V2	R5F10DPECLFB#32	R5F10PGGKFB#X5	R5F10PGGCKFB#55
R5F10DPELFB#V2G	R5F10DPECLFB#32G	R5F10PGGLFB#V5	R5F10PGGCLFB#35
R5F10DPFJFB#V2G	R5F10DPFCJFB#32G	R5F10PGGLFB#X5	R5F10PGGCLFB#55
R5F10DPFLFB#V2G	R5F10DPFCLFB#32G	R5F10PGHKFB#V5	R5F10PGHCKFB#35
R5F10DPGJFB#H2	R5F10DPGCJFB#12	R5F10PGHKFB#X5	R5F10PGHCKFB#55
R5F10DPGJFB#V2	R5F10DPGCJFB#32	R5F10PGHL721FB#H5Q	R5F10PGHCL721FB15Q
R5F10DPGJFB#V2G	R5F10DPGCJFB#32G	R5F10PGHLFB#H5	R5F10PGHCLFB#15
R5F10DPGJFB#X6	R5F10DPGCJFB#56	R5F10PGHLFB#H5Q	R5F10PGHCLFB#15Q
R5F10DPGJFB#X6G	R5F10DPGCJFB#56G	R5F10PGHLFB#V5	R5F10PGHCLFB#35
R5F10DPGLFB#H2Q	R5F10DPGCLFB#12Q	R5F10PGHLFB#V5Q	R5F10PGHCLFB#35Q
R5F10DPGLFB#V2	R5F10DPGCLFB#32	R5F10PGHLFB#X5	R5F10PGHCLFB#55
R5F10DPGLFB#V2G	R5F10DPGCLFB#32G	R5F10PGHLXXXFB#X5	R5F10PGHCLXXXFB55
R5F10DPGLFB#V2Q	R5F10DPGCLFB#32Q	R5F10PGJKFB#V5	R5F10PGJCKFB#35
R5F10DPGLFB#X6	R5F10DPGCLFB#56	R5F10PGJKFB#X5	R5F10PGJCKFB#55
R5F10DPGLFB#X6G	R5F10DPGCLFB#56G	R5F10PGJLFB#H5Q	R5F10PGJCLFB#15Q
R5F10DPJJFB#H2	R5F10DPJCJFB#12	R5F10PGJLFB#V5	R5F10PGJCLFB#35
R5F10DPJJFB#V2	R5F10DPJCJFB#32	R5F10PGJLFB#V5Q	R5F10PGJCLFB#35Q
R5F10DPJJFB#V2G	R5F10DPJCJFB#32G	R5F10PGJLFB#X5	R5F10PGJCLFB#55
R5F10DPJJFB#X6	R5F10DPJCJFB#56	R5F10PLEKFB#V5	R5F10PLECKFB#35
R5F10DPJJFB#X6G	R5F10DPJCJFB#56G	R5F10PLEKFB#X5	R5F10PLECKFB#55
R5F10DPJLFB#H2G	R5F10DPJCLFB#12G	R5F10PLELFB#H5	R5F10PLECLFB#15
R5F10DPJLFB#V2	R5F10DPJCLFB#32	R5F10PLELFB#V5	R5F10PLECLFB#35

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F10PLELFB#X5	R5F10PLECLFB#55	R5F10PMHLFB#X5	R5F10PMHCLFB#55
R5F10PLFKFB#V5	R5F10PLFCKFB#35	R5F10PMJKFB#V5	R5F10PMJCKFB#35
R5F10PLFKFB#X5	R5F10PLFCKFB#55	R5F10PMJKFB#X5	R5F10PMJCKFB#55
R5F10PLFLFB#V5	R5F10PLFCLFB#35	R5F10PMJLFB#H5Q	R5F10PMJCLFB#15Q
R5F10PLFLFB#X5	R5F10PLFCLFB#55	R5F10PMJLFB#V5	R5F10PMJCLFB#35
R5F10PLGKFB#V5	R5F10PLGCKFB#35	R5F10PMJLFB#V5Q	R5F10PMJCLFB#35Q
R5F10PLGKFB#X5	R5F10PLGCKFB#55	R5F10PMJLFB#X5	R5F10PMJCLFB#55
R5F10PLGLFB#V5	R5F10PLGCLFB#35	R5F10PPEKFB#V5	R5F10PPECKFB#35
R5F10PLGLFB#X5	R5F10PLGCLFB#55	R5F10PPEKFB#X5	R5F10PPECKFB#55
R5F10PLHKFB#V5	R5F10PLHCKFB#35	R5F10PPELFB#V5	R5F10PPECLFB#35
R5F10PLHKFB#X5	R5F10PLHCKFB#55	R5F10PPELFB#X5	R5F10PPECLFB#55
R5F10PLHLFB#H5Q	R5F10PLHCLFB#15Q	R5F10PPFKFB#V5	R5F10PPFCKFB#35
R5F10PLHLFB#V5	R5F10PLHCLFB#35	R5F10PPFKFB#X5	R5F10PPFCKFB#55
R5F10PLHLFB#V5Q	R5F10PLHCLFB#35Q	R5F10PPFLFB#V5	R5F10PPFCLFB#35
R5F10PLHLFB#X5	R5F10PLHCLFB#55	R5F10PPFLFB#X5	R5F10PPFCLFB#55
R5F10PLJKFB#H5	R5F10PLJCKFB#15	R5F10PPGKFB#V5	R5F10PPGCKFB#35
R5F10PLJKFB#V5	R5F10PLJCKFB#35	R5F10PPGKFB#X5	R5F10PPGCKFB#55
R5F10PLJKFB#X5	R5F10PLJCKFB#55	R5F10PPGLFB#H5	R5F10PPGCLFB#15
R5F10PLJLFB#H5	R5F10PLJCLFB#15	R5F10PPGLFB#V5	R5F10PPGCLFB#35
R5F10PLJLFB#H5Q	R5F10PLJCLFB#15Q	R5F10PPGLFB#V5Q	R5F10PPGCLFB#35Q
R5F10PLJLFB#V5	R5F10PLJCLFB#35	R5F10PPGLFB#X5	R5F10PPGCLFB#55
R5F10PLJLFB#V5Q	R5F10PLJCLFB#35Q	R5F10PPHKFB#V5	R5F10PPHCKFB#35
R5F10PLJLFB#X5	R5F10PLJCLFB#55	R5F10PPHKFB#X5	R5F10PPHCKFB#55
R5F10PMEKFB#V5	R5F10PMECKFB#35	R5F10PPHLFB#H5	R5F10PPHCLFB#15
R5F10PMEKFB#X5	R5F10PMECKFB#55	R5F10PPHLFB#V5	R5F10PPHCLFB#35
R5F10PMEKFB#V5	R5F10PMECKFB#35	R5F10PPHLFB#X5	R5F10PPHCLFB#55
R5F10PMEKFB#X5	R5F10PMECKFB#55	R5F10PPJKFB#H5	R5F10PPJCKFB#15
R5F10PMFKFB#V5	R5F10PMFCKFB#35	R5F10PPJKFB#V5	R5F10PPJCKFB#35
R5F10PMFKFB#X5	R5F10PMFCKFB#55	R5F10PPJKFB#V5Q	R5F10PPJCKFB#35Q
R5F10PMFLFB#V5	R5F10PMFCLFB#35	R5F10PPJKFB#X5	R5F10PPJCKFB#55
R5F10PMFLFB#X5	R5F10PMFCLFB#55	R5F10PPJKFB#X5Q	R5F10PPJCKFB#55Q
R5F10PMGKFB#V5	R5F10PMGCKFB#35	R5F10PPJLFB#H5	R5F10PPJCLFB#15
R5F10PMGKFB#X5	R5F10PMGCKFB#55	R5F10PPJLFB#H5Q	R5F10PPJCLFB#15Q
R5F10PMGLFB#V5	R5F10PMGCLFB#35	R5F10PPJLFB#V5	R5F10PPJCLFB#35
R5F10PMGLFB#X5	R5F10PMGCLFB#55	R5F10PPJLFB#V5Q	R5F10PPJCLFB#35Q
R5F10PMHKFB#V5	R5F10PMHCKFB#35	R5F10PPJLFB#X5	R5F10PPJCLFB#55
R5F10PMHKFB#X5	R5F10PMHCKFB#55	R5F10TPJFB#V2	R5F10TPJCJFB#32
R5F10PMHLFB#V5	R5F10PMHCLFB#35	R5F10TPJFB#V2G	R5F10TPJCJFB#32G

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R5F10TPJLFB#V2	R5F10TPJCLFB#32	R5F51111AGNF#U0	R5F51111AGNF#UA
R5F10TPJLFB#V2G	R5F10TPJCLFB#32G	R5F51111AGNF#W0	R5F51111AGNF#WA
R5F10TPJLFB#X6	R5F10TPJCLFB#56	R5F51113ADFK#30	R5F51113ADFK#3A
R5F10TPJLFB#X6G	R5F10TPJCLFB#56G	R5F51113ADFM#30	R5F51113ADFM#3A
R5F113GKKFB#V5	R5F113GKCKFB#35	R5F51113ADLF#U0	R5F51113ADLF#UA
R5F113GKKFB#X5	R5F113GKCKFB#55	R5F51113ADLM#U0	R5F51113ADLM#UA
R5F113GKLF#V5	R5F113GKCLFB#35	R5F51113ADNE#U0	R5F51113ADNE#UA
R5F113GLKFB#H5	R5F113GLCKFB#15	R5F51113AGNF#W0	R5F51113AGNF#WA
R5F113GLKFB#V5	R5F113GLCKFB#35	R5F51114ADFK#30	R5F51114ADFK#3A
R5F113GLKFB#X5	R5F113GLCKFB#55	R5F51114ADFL#30	R5F51114ADFL#3A
R5F113GLLFB#H5	R5F113GLCLFB#15	R5F51114ADFM#30	R5F51114ADFM#3A
R5F113GLLFB#V5	R5F113GLCLFB#35	R5F51114ADLF#U0	R5F51114ADLF#UA
R5F113GLLFB#X5	R5F113GLCLFB#55	R5F51115ADFK#30	R5F51115ADFK#3A
R5F113LKKFB#V5	R5F113LKCKFB#35	R5F51115ADLF#U0	R5F51115ADLF#UA
R5F113LKKFB#X5	R5F113LKCKFB#55	R5F51115ADNE#U0	R5F51115ADNE#UA
R5F113LLKFB#V5	R5F113LLCKFB#35	R5F51116ADFK#30	R5F51116ADFK#3A
R5F113LLKFB#X5	R5F113LLCKFB#55	R5F51116ADFL#30	R5F51116ADFL#3A
R5F113LLKFB#X5Q	R5F113LLCKFB#55Q	R5F51118ADFK#30	R5F51118ADFK#3A
R5F113LLKFB#Y2	R5F113LLCKFB#35	R5F51118ADFL#30	R5F51118ADFL#3A
R5F113LLLFB#V5	R5F113LLCLFB#35	R5F51118ADNE#U0	R5F51118ADNE#UA
R5F113MCKFB#H5	R5F113MKCKFB#15	R5F5111JADFK#30	R5F5111JADFK#3A
R5F113MCKFB#H5Q	R5F113MKCKFB#15Q	R5F5111JADFL#30	R5F5111JADFL#3A
R5F113MLKFB#V5	R5F113MLCKFB#35	R5F5111JADFM#30	R5F5111JADFM#3A
R5F113MLLFB#V5	R5F113MLCLFB#35	R5F5111JADLF#U0	R5F5111JADLF#UA
R5F113PGLFB#V5	R5F113PGCLFB#35	R5F5111JADLM#U0	R5F5111JADLM#UA
R5F113PGLFB#X5	R5F113PGCLFB#55	R5F5111JADNE#U0	R5F5111JADNE#UA
R5F113PKLFB#H5	R5F113PKCLFB#15	R5F5111JADNF#U0	R5F5111JADNF#UA
R5F113PKLFB#H5Q	R5F113PKCLFB#15Q	R5F51135ADLJ#20	R5F51135ADLJ#2A
R5F113PKLFB#X5	R5F113PKCLFB#55	R5F51136ADFM#30	R5F51136ADFM#3A
R5F113PLLFB#V5	R5F113PLCLFB#35	R5F51136ADLJ#20	R5F51136ADLJ#2A
R5F113PLLFB#X5	R5F113PLCLFB#55	R5F51137ADFM#30	R5F51137ADFM#3A
R5F113PLLFB#X5Q	R5F113PLCLFB#55Q	R5F51137ADLJ#20	R5F51137ADLJ#2A
R5F51111ADFK#30	R5F51111ADFK#3A	R5F51138ADFM#30	R5F51138ADFM#3A
R5F51111ADFM#30	R5F51111ADFM#3A	R5F51138ADLJ#20	R5F51138ADLJ#2A
R5F51111ADLF#U0	R5F51111ADLF#UA	R5F5113KADLJ#20	R5F5113KADLJ#2A
R5F51111ADLM#U0	R5F51111ADLM#UA	R7F701304EAFP#AA1	R7F701304EAFP-C#AA1
R5F51111ADNE#U0	R5F51111ADNE#UA	R7F701304EAFP#BA1	R7F701304EAFP-C#BA1
R5F51111ADNF#U0	R5F51111ADNF#UA	R7F701305EAFP#AA1	R7F701305EAFP-C#AA1

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement	Booking Part Number	Suggested Replacement
R7F701311EAFP#AA1	R7F701311EAFP-C#AA1	R7F701401EA01AFB#KA0	R7F701401EA01AFB-C#KA1
R7F701311EAFP#BA1	R7F701311EAFP-C#BA1	R7F701401EAFB#AA0	R7F701401EAFB-C#AA1
R7F701312EAFP#AA1	R7F701312EAFP-C#AA1	R7F701401EAFB#BA0	R7F701401EAFB-C#BA1
R7F701312GAFA#AA1	R7F701312GAFA-C#AA1	R7F701401EAFB#KA0	R7F701401EAFB-C#KA1
R7F701313EAFP#AA1	R7F701313EAFP-C#AA1	R7F701402E03Aafb#YR3	R7F701402EAFB-C#AA1
R7F701313EAFP#BA1	R7F701313EAFP-C#BA1	R7F701402E03Aafb#YT0	R7F701402EAFB-C#AA1
R7F701319EAFP#AA1	R7F701319EAFP-C#AA1	R7F701402EA02AFB#YT0	R7F701402EAFB-C#AA1
R7F701320EAFP#AA1	R7F701320EAFP-C#AA1	R7F701402EA12AFB#KA0	R7F701402EA12AFB-C#KA1
R7F701320EAFP#KA1	R7F701320EAFP-C#KA1	R7F701402EA14AFB#KA0	R7F701402EA14AFB-C#KA1
R7F701320EAFP#YR2	R7F701320EAFP-C#AA1	R7F701402EAFB#AA0	R7F701402EAFB-C#AA1
R7F701322EAFP#AA1	R7F701322EAFP-C#AA1	R7F701402EAFB#BA0	R7F701402EAFB-C#BA1
R7F701322EAFP#KA1	R7F701322EAFP-C#KA1	R7F701402EAFB#KA0	R7F701402EAFB-C#KA1
R7F701331AEAFP#AA2	R7F701331AEAFP#AA1	R7F701403EAFB#AA0	R7F701403EAFB-C#AA1
R7F701331AEAFP#KA2	R7F701331AEAFP#KA1	R7F701403EAFB#KA0	R7F701403EAFB-C#KA1
R7F701331EAFP#AA2	R7F701331EAFP#AA1	R7F701403EAFB#YR3	R7F701403EAFB-C#AA1
R7F701331EAFP#KA2	R7F701331EAFP#KA1	R7F701414EA03AFB#KA0	R7F701414EA03AFB-C#KA1
R7F701363EAFP#AA1	R7F701363EAFP-C#AA1	R7F701414EA03AFB#YT0	R7F701414EAFB-C#AA1
R7F701363EAFP#AAT	R7F701363EAFP-C#AAT	R7F701414EAFB#AA0	R7F701414EAFB-C#AA1
R7F701363EAFP#BA1	R7F701363EAFP-C#BA1	R7F701414EAFB#KA0	R7F701414EAFB-C#KA1
R7F701363EAFP#BAT	R7F701363EAFP-C#BAT	R7F701421EAFB#AA0	R7F701421EAFB-C#AA1
R7F701363EAFP#KA1	R7F701363EAFP-C#KA1	R7F701421EAFB#BA0	R7F701421EAFB-C#BA1
R7F701374AEAFP#AA2	R7F701374AEAFP-C#AA1	R7F701421EAFB#KA0	R7F701421EAFB-C#KA1
R7F701374AEAFP#HA2	R7F701374AEAFP-C#HA1	R7F701422EAFB#AA0	R7F701422EAFB-C#AA1
R7F701375EAFP#AA2	R7F701375EAFP-C#AA2	R7F701422EAFB#BA0	R7F701422EAFB-C#BA1
R7F701376EAFP#AA2	R7F701376EAFP-C#AA2	R7F701422EAFB#KA0	R7F701422EAFB-C#KA1
R7F701376EAFP#KA2	R7F701376EAFP-C#KA2	R7F701423EAFB#AA0	R7F701423EAFB-C#AA1
R7F701378EAFP#AA2	R7F701378EAFP-C#AA2	R7F701423EAFB#BA0	R7F701423EAFB-C#BA1
R7F701378EAFP#BA2	R7F701378EAFP-C#BA2	R7F701423EAFB#KA0	R7F701423EAFB-C#KA1
R7F701379EAFP#AA2	R7F701379EAFP-C#AA2	R7F7015023AFP#AA2	R7F7015023AFP-C#AA2
R7F701381EAFP#AA2	R7F701381EAFP-C#AA2	R7F7015264AFP#AA2	R7F7015264AFP-C#AA2
R7F701381EAFP#BA2	R7F701381EAFP-C#BA2	R7F7015264AFP#BA2	R7F7015264AFP-C#BA2
R7F701381EAFP#KA2	R7F701381EAFP-C#KA2	R7F7015264AFP#KA2	R7F7015264AFP-C#KA2
R7F701382EAFP#AA2	R7F701382EAFP-C#AA2	R7F7015273AFP#AA2	R7F7015273AFP-C#AA2
R7F701382EAFP#KA2	R7F701382EAFP-C#KA2	R7F7015273AFP#KA2	R7F7015273AFP-C#KA2
R7F701390EAFP#AA2	R7F701390EAFP-C#AA1	R7F7015303AFP#AA2	R7F7015303AFP-C#AA2
R7F701390EAFP#HA2	R7F701390EAFP-C#HA1	R7F7015303AFP#BA2	R7F7015303AFP-C#BA2
R7F701400EAFB#KA0	R7F701400EAFB-C#KA1	R7F7015313AFP#AA2	R7F7015313AFP-C#AA2
R7F701401EA00AFB#KA0	R7F701401EA00AFB-C#KA1	R7F7015313AFP#KA2	R7F7015313AFP-C#KA2

Appendix: Digi-Key Affected Part List (cont.)

Booking Part Number	Suggested Replacement
R7F7015443AFP#AA2	R7F7015443AFP-C#AA2
R7F7015443AFP#KA2	R7F7015443AFP-C#KA2
R7F7015483AFP#AA2	R7F7015483AFP-C#AA2
R7F7015483AFP#KA2	R7F7015483AFP-C#KA2
R7F7015484AFP#KA2	R7F7015484AFP-C#KA2
R7F7015484AFP#KA6	R7F7015484AFP-C#KA6
R7F7015653AFP#KA2	R7F7015653AFP-C#KA2
R7F7015683AFP#KA2	R7F7015683AFP-C#KA2
R7F7015693AFP#KA2	R7F7015693AFP-C#KA2
R7F701A293AFP#KA2	R7F701A293AFP-C#KA2
R7F701A303AFP#AA2	R7F701A303AFP-C#AA2
R7F701A303AFP#KA2	R7F701A303AFP-C#KA2
READ2302GSP#GC0	READ2304GSP
RNA51953AP#T0	REAR56953AGSM
RNA51953BP#T0	REAR56953BGSMB
RNA51957BP#T0	REAR56957BSGMB
RNA51958AFP#H0	REAR56958BSGMB
RNA51958BP#T0	REAR56958BSGMB