



Micron Technology, Inc.  
8000 S. Federal Way  
PO Box 6  
Boise, ID United States

## EOL of Select SDR, DDR2, DDR3, and DDR4 Marketing Part Numbers

PCN: 32332

Published: 2017-06-06

<b>Type:</b>	End of Life
<b>Description:</b>	Micron is announcing the EOL of a select group of DRAM Marketing Part Numbers
<b>Reason:</b>	Change in Market Demand
<b>Product Affected:</b>	Specific SDR, DDR2, DDR3 and DDR4 MPNs listed below

<b>Affected Micron Part Number</b>	<b>Recommended Replacement</b>	<b>Customer Part Number</b>
<u>Component</u>		
MT40A2G8FSE-083E:A	MT40A2G8NRE-083E:B	
MT40A2G8FSE-093E:A	MT40A2G8NRE-083E:B	
MT40A4G4FSE-083E:A	Contact Factory	
MT41J128M16JT-093 J:K	Contact Factory	
MT41J128M8DA-093:J	Contact Factory	
MT41J256M8DA-107:K	MT41J256M8DA-093:K	
MT41K512M8RG-093:N	MT41K512M8DA-093:P	
MT48LC2M32B2B5-6A AAT:J	Contact Factory	
MT48LC8M16A2P-7E AIT:L	MT48LC8M16A2P-7E IT:L	
<u>Module</u>		
MT18JDF1G72PZ-1G9P1	MT18JDF1G72PDZ-1G9P1	

MT18JSF1G72PDZ-1G9N1	MT18JSF1G72PDZ-1G9P1	
MT18JSF1G72PZ-1G9P1	MT18KSF1G72PZ-1G6P1	
MT18JSF25672AZ-1G4J2	MT9JSF25672AZ-1G4K1	
MT18JSF51272PDZ-1G6K1	MT18KSF51272PDZ-1G6K1	
MT18JSF51272PZ-1G4K1	MT9KSF51272PZ-1G6P1	
MT18JSF51272PZ-1G6K1	Contact Factory	
MT18JSF51272PZ-1G9K1	Contact Factory	
MT18KSF1G72PDZ-1G4P1	MT18KSF1G72PDZ-1G6P1	
MT18KSF1G72PDZ-1G6N1	MT18KSF1G72PDZ-1G6P1	
MT18KSF1G72PZ-1G6N1	MT18KSF1G72PZ-1G6P1	
MT18KSF51272AZ-1G6K3	MT18KSF51272AZ-1G6K1	
MT18KSF51272PZ-1G6K2	Contact Factory	
MT36HTF1G72PZ-667C1	Contact Factory	
MT36HTF1G72PZ-80EC1	Contact Factory	
MT36HVZS1G72PZ-667C1	Contact Factory	
MT36JSF1G72PZ-1G6K1	Contact Factory	
MT36JSF1G72PZ-1G9K1	MT18JSF1G72PDZ-1G9P1	
MT36JSF2G72PZ-1G6P1	MT36KSF2G72PZ-1G6P1	
MT36JSF51272PZ-1G4J1	Contact Factory	
MT36KSF1G72PZ-1G6K2	MT18KSF1G72PZ-1G6P1	
MT4HTF6464AZ-800M1	Contact Factory	
MT72KSS4G72PZ-1G4N1	Contact Factory	
MT9HTF6472PKZ-667H1	Contact Factory	
MT9HTF6472PZ-667H1	Contact Factory	
MT9JSF25672PZ-1G6K1	MT9KSF25672PZ-1G6K1	
MT9JSF51272PZ-1G9P1	Contact Factory	
MT9KSF25672PZ-1G4K1	MT9KSF25672PZ-1G6K1	

MTA18ASF1G572PDZ-2G3111	MTA18ASF1G572PDZ-2G6221
MTA18ASF1G72AZ-2G1B1	MTA18ASF1G72AZ-2G3B1
MTA18ASF1G72PDZ-2G1B1	MTA18ASF1G72PDZ-2G3B1
MTA18ASF1G72PZ-2G1B1	MTA18ASF1G72PZ-2G3B1
MTA18ASF2G72AZ-2G1A1	MTA18ASF2G72AZ-2G3B1
MTA18ASF2G72AZ-2G1B1	MTA18ASF2G72AZ-2G3B1
MTA36ASF4G72LZ-2G3A1	MTA36ASF4G72LZ-2G6D1
MTA36ASF4G72PZ-2G1B1	MTA36ASF4G72PZ-2G3B1
MTA72ASS8G72LZ-2G3A1	MTA72ASS8G72LZ-2G3B2
MTA8ATF1G64AZ-2G1A1	MTA8ATF1G64AZ-2G1B1
MTA8ATF1G64HZ-2G1A1	MTA8ATF1G64HZ-2G3A1
MTA9ASF1G72AZ-2G1B1	MTA9ASF1G72AZ-2G3B1
MTA9ASF51272AZ-2G1B1	MTA9ASF51272AZ-2G3B1
MTA9ASF51272PZ-2G1B1	MTA9ASF51272PZ-2G3B1
<u>Wafer</u>	
MT41K512M8V90BWC1	Contact Factory

\*Materials that have been ordered are in **bold**.

---

<b>Method of Identification:</b>	Marketing Part Number
<b>Micron Sites Affected:</b>	All Sites
<b>Qualification Plan:</b>	Suggested replacement parts have been qualified according to Micron's standard qualification processes.
<b>Last Purchase Date*:</b>	2017-12-06
<b>Last Shipment Date:</b>	2018-06-06

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

**Micron Confidential and Proprietary Information**

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.